



**Figure 3.12** Techniques for reducing stress concentration in stepped shaft with bearing: (a) with corner radius only; (b) undercut; (c) inserted ring; (d) undercut to simulate a ring; (e) relief groove; (f) relief groove.