Graph Digitizer

Graph Title:

Chart 3.10 Stress concentration factors for bending of a stepped bar of circular cross section with a shoulder fillet (based on photoelastic tests of Leven and Hartman 1951; Wilson and White

Curve Navigation: 1 of 1 Hide

Curve Symbol:

Curve Label: Curve 1

X Axis: r/d

X Significant Digits: 4

Y Axis: Kt

Y Significant Digits: 4

To digitize the curve:
1. Move mouse along the curve; click to save X/Y values in the table.
2. Modify Curve Label, if desired.
3. Click for a new curve.
4. To delete a point, click on it or delete corresponding table row.

X	Y
0.1030	1.703
0.1670	1.548
0.2992	1.322

Clear All

Zoom 50% 100% 150% 200%



To drag the image or a point press the Ctrl key, click on the object, and then release the Ctrl key. Show: Active Area